

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: Equipment

DATE OCCURRED 04-06-98

DATE REPORTED 04-06-98

TIME OCCURRED 0630 hrs

TIME REPORTED 0630 hrs

LOCATION(S) OF OCCURRENCE:

Police/Aircraft Rescue Station - Bay #2 - 8190 E. Marginal Way S.

REPORTED BY:

PHONE NO(S):

Barden - 00115

SUMMARY:

The fire apparatus air compressor located to the rear of bay #2 is malfunctioning. The HVAC technician was notified and will contact a Quincy compressor technician to respond and repair. Unknown down time. Until further notice, do not couple the air supply lines to FD-1 or FD-2. The compressor has been shut down and without back air pressure the air eject will malfunction causing damage to the line. Until repair is made both fire apparatus will need to be "fired up" approximately every 2-3 hours to maintain air pressure.

OFFICERS: Barden, J.R. - 00115 JB

ACTION: Out of Service (compressor) - Until further notice